

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.15**SOURCE INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** SIR-000695**Date Inspected:** 27-Jun-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 0**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 12**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Changxing Dao, Shanghai

Quality Control Contact:	ABF Paint Supervisor William (Bill) Oak			Quality Control Present:	Yes	No
Material transfer:	Yes	No	N/A	Sampled Items:	Yes	No N/A
Stock Transfer:	Yes	No	N/A	OK to Cut:	Yes	No N/A
Rebar Test Witness:	Yes	No	N/A	Delayed/Cancelled:	Yes	No N/A
Other:	Surface Preparation and Coatings Application					
Bridge No:	34-0006			Component:	OBG Misc. Metal	
Bid Item:	77,78,79,80			Lot No:	B226	

Summary of Items Observed:

On this date Caltrans Office of Structural Materials (OSM) Quality Assurance (QA) NACE III coating inspector, Mr. Donald Jordan arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island in Shanghai, China. The purpose of the coating inspections are to monitor the surface preparation and coating applications for the SAS Bay Bridge project. This QA NACE III coating inspector observed the following:

The following inspections were performed by Caltrans QA Coatings Inspector Jordan, American Bridge/Fluor Enterprises, a JV (ABF) Paint Supervisors William (Bill) Oak and Don Walton, ABF QC Zhou Qun Song (Joe), ABF QC David Duon, ABF QC Shi Zhaoyuan (Stone), ABF QC Zhou Wei, ABF QC Wei Chang Yun, ABF QC Sun Xiong, International Paint (IP) Onsite Technical Services Engineer (OTSE) Peng Zi Li, IP OTSE Alpha Chen, Zhenhua Port Machinery Company, LTD (ZPMC) QC Manager Xia Yong, ZPMC QC Zhang Diang, ZPMC QC Dong Yao Fei and ZPMC QC Guo Wan Li, ZPMC QC Xie Yong Gang, ZPMC QC An Ming, ZPMC QC Dong Ji Fang and ZPMC QC Xia Yu Juan.

All Notices of Inspection and Quality Control (QC) Inspection reports signed by Mr. Jordan on this date identify receipt of the documentation and are not intended to be identified as acceptance or rejection of the work performed.

OBG Miscellaneous Metal

Caltrans QA Coatings Inspectors received Notices of Inspection to attend joint inspections with ABF and ZPMC QC for surface preparation prior to coating touch up repairs on suspender brackets. The inspection was canceled due to rain.

SOURCE INSPECTION REPORT

(Continued Page 2 of 2)

Fabrication on assembled components of the OBG's and Towers are not complete. Outstanding weld repairs have not been performed. Coating damage requiring re-blast is expected.

Summary of Conversations:

There were no relevant conversations on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh (China) +8613472477571, who represents the Office of Structural Materials for your project.

Inspected By:	Jordan,Don	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
